

Application Note: AN10001

How to pass alias pointer arguments

This application note is a short how-to on programming/using the xTIMEcomposer tools. It shows how to pass alias pointer arguments.

Required tools and libraries

This application note is based on the following components:

- xTIMEcomposer Tools - Version 14.0.0

Required hardware

Programming how-tos are generally not specific to any particular hardware and can usually run on all XMOS devices. See the contents of the note for full details.